

DART**RELEASED**
100507

PPP

Part Number Description Box Part Number Dimension Other Packaging Dimension Logo Decals **Packaging Instructions and Decal Placement****D412-694-017**

Tape box securely with clear tape. Add foam to bottom of box. Add kit and paperwork to box. Close box with clear tape. Apply label D2729-3 as per instructions in QSI 014 section 4.5.

D2729-1**N/A**
*100507***D2729-3**

H:\Admin-qa\iso\forms\PPP-1.Rev.A